


# True Union 2000 Ball Valve Retrofit Kit INSTALLATION INSTRUCTIONS




RFK-3A-1000

Retrofit Kit is designed for in-line replacement of other brand ball valves with Spears True Union 2000 Ball Valves. Kit includes one pair (2) extended socket-type end connectors with O-rings installed. The following instructions are to be used in addition to installation instructions included with new valve. Read all instructions before proceeding.



BALL VALVE FOR REPLACEMENT



PIPE LAYING LENGTH AFTER CUTTING

TRUE UNION 2000 BALL VALVE INSTALLED WITH RETROFIT KIT

Size	1/2	3/4	1	1-1/4	1-1/2	2	2-1/2	3	4
L	5-5/16	6-1/4	6-11/16	7-1/8	8-3/16	5-15/16	12	12-1/16	13-3/16

L ± 1/16

- Step 1: Mark and cut old valve from line according to specified "L" dimension in chart. Pipe ends must be cut square.
- Step 2: Deburr and bevel pipe ends. All burrs on the pipe O.D and I.D must be removed. The O.D should be beveled 10° to 15°.
- Step 3: Remove union nuts from new True Union 2000 Ball Valve and slide over pipe making sure the nut threads will face the valve when installed.
- Step 4: Install Retrofit Kit end connectors according to solvent cement welding procedures included with valve. End connector socket must be fully seated on pipe. Allow to properly cure before proceeding. DO NOT allow primer or cement to come in contact with the end connector O-ring face, union nuts, or other internal valve components.
- Step 5: Install new True Union 2000 Valve cartridge between newly installed retrofit end connectors according to installation instructions included with new valve. DO NOT use union nuts to draw together any gaps between end connector and valve. Free system components to compensate if necessary.



### SPEARS® MANUFACTURING COMPANY • CORPORATE OFFICE

15853 Olden St., Sylmar, CA 91342 • PO Box 9203, Sylmar, CA 91392 (818) 364-1611 • www.spearsmfg.com



15860 Olden St. Sylmar (Los Angeles), CA 91342 (818) 364-1611 • (800) 862-1499 Fax (818) 367-3014

### NORTHWEST 4103 C St. NE Suite 200

Auburn (Seattle), WA 98002 (253) 939-4433 • (800) 347-7327 Fax (253) 939-7557

#### ROCKY MOUNTAIN 4880 Florence St.

Denver, CO 80238 (303) 371-9430 • (800) 777-4154 Fax (303) 375-9546

#### SOUTH CENTRAL

1000 Lakeside Parkway Flower Mound, TX 75208 (469) 528-3000 • (800) 441-1437 Fax (469) 528-3001

### UTAH

5395 West 1520 South Salt Lake City, UT 84104 (303) 371-9430 • (800) 777-4154 Fax (303) 375-9546

### NORTHEAST

590 Industrial Dr., Suite 100 Lewisberry (Harrisburg), PA 17339-9532 (717) 938-8844 • (800) 233-0275 Fax (717) 938-6547

### SOUTHEAST

4205 Newpoint Pl., Suite 100 Lawrenceville (Atlanta), GA 30043 (678) 985-1263 • (800) 662-6326 Fax (678) 985-5642

## FLORIDA

9563 Parksouth Court Orlando, FL 32837 (407) 843-1960 • (800) 327-6390 Fax (407) 425-3563

#### MIDWEST

1 Gateway Ct., Suite A Bolingbrook (Chicago), IL 60440 (630) 759-7529 • (800) 662-6330 Fax (630) 759-7515

#### INTERNATIONAL SALES

15853 Olden St. Sylmar (Los Angeles), CA 91342 (818) 364-1611 • Fax (818) 898-3774