

# CERTIFICATE OF CONFORMITY



## 1. PRODUCT: MDX-R3 VGB COMPLIANT DEBRIS DRAIN

MDX-R3 US  
XXX-262-2240-XX CONCRETE ADJUSTABLE  
XXX-262-2243-XX CONCRETE NON ADJUSTABLE  
XXX-272-2240-XX VINYL  
XXX-282-2240-XX FIBERGLASS  
MDX-R3 AU  
XXX-262-2241-XX CONCRETE ADJUSTABLE  
XXX-262-2244-XX CONCRETE NON ADJUSTABLE  
XXX-272-2241-XX VINYL  
XXX-282-2241-XX FIBERGLASS  
MDX-R3 EU  
XXX-262-2242-XX CONCRETE ADJUSTABLE  
XXX-262-2245-XX CONCRETE NON ADJUSTABLE  
XXX-272-2242-XX VINYL  
XXX-282-2242-XX FIBERGLASS  
-XX DESIGNATES COLOR

The MDX-R3 VGB Compliant Debris Drain is a 14" diameter drain fitting. It includes a sump, an enlarged suction element and a reducer adapter to 2 1/2" with a funnel shaped cover that is affixed to a concrete leveling ring or directly to the sump. The drain has a single C shaped opening to accept large debris.

## 2. APPLICABLE STANDARD OR REGULATION:

VGB Pool and Spa Safety Act 2008  
ASME A112.19.8-2009B  
ANSI/APSP-7 2006

## 3. DOMESTIC MANUFACTURER:

Paramount Leisure Industries  
DBA/ Paramount Pool and Spa Systems  
295 E Corporate Plc #100  
Chandler, AZ 85225  
480-893-7607  
800-621-5886

## 4. US IMPORTER: N/A

## 5. PRIVATE LABELER: N/A

## 6. Test Record Documentation:

Dominic Conn  
Director of Engineering  
Paramount Pool and Spa Systems  
Chandler, AZ 85225  
dconn@1paramount.com  
480-893-7607x250  
Tony Zhou  
IAPMO R&T Lab  
Manager Testing  
5001 East Philadelphia Street  
Ontario, CA 91761  
tony.zhou@iapmortl.org  
909-472-4243

## 7. Date and Place of Manufacture:

October 2010  
Chandler AZ

## 8. Date and Location of Test Report:

September 28, 2010  
IAPMO R&T Lab

## 9. Name of Third Party laboratory:

IAPMO R&T Lab  
5001 East Philadelphia Street  
Ontario, CA 91761-2816 USA