

# CERTIFICATE OF CONFORMITY



ANTI-ENTRAPMENT DEBRIS DRAIN

**1. PRODUCT: MDX2 ANTI-ENTRAPMENT DEBRIS DRAIN**

XXX-202-2210-XX CONCRETE  
XXX-212-2210-XX VINYL  
XXX-222-2210-XX ONE-PIECE LOW  
FIBERGLASS  
XXX-202-2221-XX RETRO  
CONCRETE VINYL FIBER  
-XX DESIGNATES COLOR

The MDX2 Anti-Entrapment Debris Drain is a 13"-16" rectangular drain fitting. It includes a sump and 2 1/2" pipe with a rectangular raised cover that is affixed to a concrete leveling ring or directly to the sump. The drain has two straight openings at opposite ends to accept large debris.

**2. APPLICABLE STANDARD OR REGULATION:**

VGB Pool and Spa Safety Act 2008  
ASME A112.19.8-2008a  
ANSI/APSP-7 2006

**3. DOMESTIC MANUFACTURER:**

Paramount Leisure Industries  
DBA/ Paramount Pool and Spa Systems  
295 E Corporate Place #100  
Chandler, AZ 85225  
480-893-7607  
800-621-5886

**4. US IMPORTER: N/A**

**5. PRIVATE LABELER: N/A**

**6. Test Record Documentation:**

Dominic Conn  
Director of Engineering  
Paramount Pool and Spa Systems  
Chandler, AZ 85225  
dconn@1paramount.com  
480-893-7607 x250  
Kris Adilukito P.E.  
IAPMO R&T  
Manager Testing and QA  
5001 East Philadelphia Street  
Ontario, CA 91761  
kris.adilukito@iapmortl.org  
909-472-4124

**7. Date and Place of Manufacture:**

November 2008  
Chandler, AZ

**8. Date and Location of Test Report:**

Nov 6, 2008  
IAPMO R&T Lab

**9. Name of Third Party laboratory:**

IAPMO R&T Lab  
5001 East Philadelphia Street  
Ontario, CA 91761-2816 USA